

Memo

To: File – Jiffy Lube, 850 E. Kearney
From: Gene Pabst
CC:
Date: 10/03/06
Re: Sewer Maintenance – Oil in the sanitary sewer

On Sept. 27, 2006 Bob Leazure, Sewer Maintenance, informed me that he had been doing routine cleaning on the sanitary sewer line in front of Jiffy Lube, 850 E. Kearney, and found oil in the sanitary sewer. He said that there was a partial blockage also. He did not say what the blockage was. On October 3, 2006 (9:30 A.M.) I inspected the Jiffy Lube. I talked to Kurt Caudill, Store Manager, about the oil. He said that they have not lost any large amounts of oil. They do have minor spillage but that is cleaned up with oil dry. He stated that they also wet mop the floors. I walked through the facility. It was very clean. The basement used to have several floor grate but they have been concreted in. I did not see a sump pump. The basement floor had a couple of places with minor oil spillage. They have their bulk oil and used oil storage in the basement. I figured the floor grates were concreted in as a means of spill protection. I did not see anything out of the ordinary for the facility. Mr. Caudill stated that he has only been Store Manager for about a month. He came from another store. He said that the previous manager had everything messed up. We talked about being aware of what goes down the drain. I also gave him a copy of Chapter 120.

850 E. Kearney